Capito, Bonnie P CIV NAVFAC Lant

From: Sent: Cole, Linda L CIV NAVFAC MidAtlantic Wednesday, January 03, 2007 1:56 PM Capito, Bonnie P CIV NAVFAC Lant

To: Subject:

ARF - NWSY Cheatham Annex Site 11 (Bone Yard)

Bonnie,

Please find included in the string of emails EPA Region 3 hydrologist's comment(s) on the Revised Draft RI for CAX Site 11.

Happy New Year!

Linda

----Original Message-----

From: Franklin.Greyson@epamail.epa.gov [mailto:Franklin.Greyson@epamail.epa.gov]

Sent: Friday, December 29, 2006 8:11

To: djoiner@mbakercorp.com; Cole, Linda L CIV NAVFAC MidAtlantic;

Marlene.Ivester@CH2M.com; damiller@deq.virginia.gov; Laura.Cook@CH2M.com

Subject: Fw: Remedial Investigation for NSW Yorktown Cheathan Annex Site 11 - Hydro

Comment

Greyson Franklin NPL/BRAC Federal Facilities Branch USEPA Region 3 (3HS11) 1650 Arch Street Philadelphia, PA 19103 Phone # 215-814-2333 FAX # 215-814-3051 franklin.greyson@epa.gov

---- Forwarded by Greyson Franklin/R3/USEPA/US on 12/29/2006 08:10 AM

Herminio

Concepcion/R3/US

EPA/US

Greyson Franklin/R3/USEPA/US

CC

To

12/12/2006 10:22

AM

Subject

Fw: Remedial Investigation for NSW Yorktown Cheathan Annex Site

11

Hi Greyson;

I'm sorry; I made a mistake in my comment. Instead of down gradient is up gradient. My comment still applied because there is a data gap in this area. The comment must be:

1) The report states in Section 5.5.3 Groundwater page 5-5 that "only two wells had inorganic contaminants exceeding screening criteria. Monitoring well 11GW 01 exceeded screening criteria for total and dissolved compounds of arsenic, iron and manganese. The sample

collected from 11GW05 exceeded screening criteria for total and dissolved arsenic". However, both 11GW01 and 11GW05 are the most up gradient wells from the site, and also there are no wells in between these two wells. I recommend collecting few direct push groundwater samples to determine the extent and magnitude of the contamination and to fill the dada gaps.

Thanks,

Herminio Concepcion
Environmental Protection Agency
Geologist
Hazardous Site Cleanup Division
Telephone - (215) 814-3115
---- Forwarded by Herminio Concepcion/R3/USEPA/US on 12/12/2006 10:14 AM ----

Herminio Concepcion/R3/US EPA/US

To Greyson Franklin/R3/USEPA/US

CC

12/12/2006 09:40

AM

Subject

Remedial Investigation for NSW Yorktown Cheathan Annex Site 11

I have reviewed the Remedial Investigation for NSW Yorktown Cheathan Annex Site 11 and I have the following comment for your consideration;

1) The report states in Section 5.5.3 Groundwater page 5-5 that "only two wells had inorganic contaminants exceeding screening criteria. Monitoring well 11GW 01 exceeded screening criteria for total and dissolved compounds of arsenic, iron and manganese. The sample collected from 11GW05 exceeded screening criteria for total and dissolved arsenic". However, both 11GW01 and 11GW05 are the most down gradient wells from the site, and also there are no wells in between these two wells. I recommend collecting few direct push groundwater samples to determine the extent and magnitude of the contamination and to fill the dada gaps.

Herminio Concepcion Environmental Protection Agency Geologist Hazardous Site Cleanup Division Telephone - (215) 814-3115